LIST OF TEMPORARY EXEMPTIONS FROM JULY 2025 - JULY 2026

AIRWORTHINESS

Reference CAV/AIRC /08	Date	Registration	Description	NTO	MK REF	Status
1941	04/07/2025	3B-NCL	REQUEST TO EXTEND MEL 33-20-01A NO SMOKING/FASTEN SEAT BELT SIGN INOP BY FURTHER 10 DAYS DUE TO PISA NOT AVAILABLE		NCL-033-25	Closed
1942	11/07/2025	3B-NCE	REQUEST TO EXTEND DEADLINE OF MP TASK 215200-00M05-01(PACKS AIR GENERATION - AGU RH) [TS704003R384] BY FURTHER 800 FH BEYOND AMP APPROVAL DUE TO SHORTAGE OF SPARE RAM AIR INLET (RAI) ASSEMBLIES		NCE-029-25	Closed
1943	28/07/2025	3B-NBP	REQUEST AUTHORISATION TO EXTEND MEL 23-28-01B CAT C "COM SATCOM FAULT" BY 10 ADDITIONAL DAYS DUE UNAVAILABILITY OF PART, ANTENNA HIGH GAIN SATCOM P/N: 822-2923-050		NBP-025-25	Closed
1944	05/08/2025	3B-NBQ	One off authorisation for LAE to carry out inspection of NST on external power receptacles		NBQ-028-25	Closed
1945	13/08/2025	3B-NBG	Request Authorisation to extend MEL 20-11-02 CAT B Airframe air bleeds. Deadline 13 August 2025 by additional 3 days due further troubleshooting required and 3B-NBN and in RRG.		NBG-022-25	Closed
1946						Not used
~~1947~~	~~03/09/2025~~	~~3B-NBU~~	~~One off authorisation for LAE to apply MEL 47-10-01A Cat C on Aircraft~~	-	~~NBU-042-25~~	Not used

1948	03/09/2025	3B-NBU	One off authorisation for LAE to apply MEL 47-10-01A Cat C on Aircraft		NBU-042-25	Closed
1949	09/09/2025	3B-NBV	Extension of Task LDCMR		NBV-040-25 NBV-041-25	Closed
1950	26/09/2025	3B-NBU	Extension MEL Item 32-42-03		NBU-045-25	Closed
1951	29/09/2025	3B-NCF	EXTENSION OF AMP Task 27440-00M02-01 and 274400-00m03-01 BY FURTHER 500FH BEYOND AMP APPROVAL DUE TO UNAVAILABILITY OF TOOLS		NCF-038-25	Closed
1952	17/10/2025	3B-NCL	REQUEST AUTHORISATION TO EXTEND MEL 25-20-01B CAT D "SEAT 3K ELECTRICAL & MANUAL FUNCTION INOP" BY 120 ADDITIONAL DAYS DUE MOTORS+ELECTROMAGNET P.N P79963-M02 STILL ON ORDER		NCL-052-25	Closed
1953	04/11/2025	3B-NCF	REQUEST AUTHORISATION TO INSTALL AFT DRAIN MAST CONFIRM UNSERVICABLE TO OPERATE FERRY FLIGHT MK003 TO AVH FOR C-CHECK. THE SYSTEM WILL BE DEACTIVATED AND MEL APPLIED MEL 30-71-01A		NCF-044-25	Closed
1954	06/11/2025	3B-NCU	Authorisation to re use nuts (item 9) ref MP ATR-A-38-31-20-01001-720A-A & ATR 00271168 req IP		NCU-005-25	Closed
1955	12/11/2025	3B-NBQ	Request to extend MEL		NBQ-042-25	Closed
1956	26/11/2025	3B-NBV	Dispatch aircraft as per Rolls-Royce following Boroscope		NBV-045-25	Closed
1957	05/12/2025	3B-NBP	Extension MEL CAT C 34-71-06A		NBP-036-25	Closed

1958	24/12/2025	3B-NCP	TO EXTEND DEADLINE OF AMP TASK 562101-DU1-10000-2 (CABIN WINDOWS) TS7040044F0B BY ONE MONTH BEYOND AMP ALLOWABLE EXTENSION IN ORDER TO CARRY OUT TASK IN C-CHECK WITH WALL PANELS REMOVED.		NCP-049-25	Closed
1959	05/01/2026	3B-NBP	Extension MEL 27-51-07A		NBP-002-26	Closed
1960	22/02/2026	3B-NCL	TO EXTEND DEADLINE FOR LANDING GEAR OVERHAUL AND ASSOCIATED AMP TASKS IN ATTACHED APPENDIX A BY 3 MONTHS BEYOND ALLOWANCE EXTENSION IN AMP AS PER AMPES 81569916-2026-1--01 DUE TO UNAVAILABILITY OF LANDING GEAR		NCL-002-26	Closed
1961	24/02/2026	3B-NCC	EXEMPTION ON THE TIME BETWEEN OVERHAUL (TBO) THRESHOLD OF 4000FH ON THE AVIA PROPELLER LTD PN V510 AND SN 940681278 DUE TO KATE DELIVERY OF A SPARE PROPELLE ASSEMBLY		AIR-TEC	Closed
1962	03/03/2026	3B-NBP	Extension to deviate from AMM Procedure		NBP-014-26	Closed
1963	06/03/2026	3B-NBP	REQUEST ONE OFF APPROVAL TO APPLY HIGH SPEED TAPE ON PANEL 334BB DUE SEALANT NOT AVAIL. SAME APPROVED BY AIRBUS UNDER RDAF REF 81756405/003/2026 ISSUE A LIMITED TO 5 FC		NBP-015-26	Closed

1964	20/03/2026	3B-NBP	REQUEST AUTHORISATION TO RELEASE AIRCRAFT AS PER TECH REQUEST 81765467/013 - PANEL 193RB GROUND DOOR OPERNING HANDLE CRACK FOR 50 FC		NBP-017-26	Closed
1965	31/03/2026	3B-NBU	Request authorisation to use previous AMM Oct 25 due to bug in AMM Apr 26		NBU-014-26	Closed
1966	27/04/2026	3B-NBG	Request authorisation to extend MEL 30-11-02 CAT B by additional 03 days DE-ICE AIRFRAME FAUKT" due unavailability of part and same on order		NBG-022-26	Closed
1967	08/05/2026	3B-NBP	REQUEST TO EXTEND MEL 31-19-07A CAT A "STS PB ON THE ECP INOP" BY ADDITIONAL 03 FC AS PER ADOM REF:V31D26018405 ISSUE 1 DUE UNAVAILABILTY OF INTEGRATED CONTROL PANEL ENG START PN 727-7312-06 AND SAME ON ORDER		NBP-025-26	Closed
1968	10/05/2026	3B-NBP	PB ON ECAM CONTROL PANEL NOT OPERATING CORRECTLY (INTERMITTENT) & MEL 31-19-07A WAS APPLIED ON 8TH MAY 2026. MAU REQUEST YOUR AUTHORISATION TO FURTHER EXTEND MEL BY 06 ADDITIONAL DAYS STARTING 1ST EXTENSION		NBP-026-26	Closed
1969	14/05/2026	3B-NBU	Request to extend MEL 33-20-02A		NBV-013-26	Closed
1970	22/05/2026	3B-NCE	REQUEST TO APPLY HIGH SPEED TAPE 150 APPLING SEALANT AFTER INSTALLATION OF PANEL 334BB REF		NCE-018-26	Closed

			MP-350-A-55-22-71-00ZZZ-720Z-A RDA F81802514/009/2026 ISSUE A			
1971	22/05/2026	3B-NBV	Request to extend MEL 33-20-02A		NBV-029-26	Closed
1972	05/06/2026	3B-NCF	Due no dataplate for APU Air Intake flap. Request to use Airbus PMS 01-06-12 for re-identification of APU intake flap following SB Honeywell HBT1700-49-8408 Paragraph 3F		NCF-016-26	Closed
1973	12/06/2026	3B-NCF	Cannot comply with VSB29130-73-44-010 Rev 4 May 202 Paragraph 4C and 4D(2)(b) due to Software Upload Issue to CWAP.		NCF-022-26	Closed

FLIGHT OPERATIONS

Reference CAV/FOI /XX	Date	Registration	Description	NTO	MK REF	Status
NIL						

PERSONNEL LICENSING

Reference CAV/PEL /XX	Date	Registration	Description	NTO	MK REF	Status
NIL						

AERODROME

Reference CAV/PEL /XX	Date	Registration	Description	NTO	MK REF	Status
NIL						